



DIR-880L Firmware Patch Notes

Firmware: 1.20B02 BETA01_icl9

Hardware: Ax

Date: December 21, 2018

Report:

A research report to D-Link has reported multiple routers (DIR-850L A1/B1, DIR-822 C1 and DIR-880L A1) with security vulnerabilities: Authenticated bypass and Authenticated RCE.

3rd Party Researcher: Henry Huang (happyholic1203 at gmail dot com)

Problems Fixed:

1. Authentication bypass
 2. Authenticated RCE
-